

Stormwater Management Culvert Inventory



Town of Pelham, Massachusetts

Date: June 3, 2019

Date of Inspections: Winter 2018



This page left intentionally blank

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-109-I
Street Name:	BUFFUM ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/12/2018
Culvert Condition:	Poor
Culvert Diameter:	28
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	Pipe invert rusted out
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	Yes
Wingwall Material:	Stone
Wingwall Length:	70
Wingwall Condition:	Fair
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	29
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	12
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-109-O
Street Name:	BUFFUM ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/12/2018
Culvert Condition:	Poor
Culvert Diameter:	28
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	Pipe invert rusted out
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	Yes
Wingwall Material:	Stone
Wingwall Length:	70
Wingwall Condition:	Fair
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	29
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	12
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-110-I
Street Name:	SHUTESBURY ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/13/2018
Culvert Condition:	Good
Culvert Diameter:	36
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Good
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	None
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	144
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-110-O
Street Name:	SHUTESBURY ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/13/2018
Culvert Condition:	Good
Culvert Diameter:	36
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Good
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	None
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	144
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-111-I
Street Name:	BUFFUM ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/12/2018
Culvert Condition:	Poor
Culvert Diameter:	12
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Good
Headwall Material:	Stone
Wingwall Present:	Yes
Wingwall Material:	Stone
Wingwall Length:	36
Wingwall Condition:	Good
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	7
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	24
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-111-O
Street Name:	BUFFUM ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/12/2018
Culvert Condition:	Poor
Culvert Diameter:	12
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	Pipe bottom rusted out
Headwall Present:	No
Headwall Condition:	None
Headwall Material:	None
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	27
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	24
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-112-I
Street Name:	BUFFUM ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/12/2018
Culvert Condition:	Good
Culvert Diameter:	0
Culvert Height:	28
Culvert Width:	40
Culvert Shape:	Other
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	Yes
Wingwall Material:	Stone
Wingwall Length:	24
Wingwall Condition:	Fair
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	23
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	12
Side Slopes	Sloped
Underground Utilities:	Yes

Outfall ID:	CUL-112-O
Street Name:	BUFFUM ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/12/2018
Culvert Condition:	Good
Culvert Diameter:	0
Culvert Height:	28
Culvert Width:	40
Culvert Shape:	Other
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	23
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	12
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-118-I
Street Name:	SHUTESBURY ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/13/2018
Culvert Condition:	Poor
Culvert Diameter:	18
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	Pipe bottom rusted
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	16
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	24
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-118-O
Street Name:	SHUTESBURY ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/13/2018
Culvert Condition:	Fair
Culvert Diameter:	18
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	Pipe bottom rusted
Headwall Present:	No
Headwall Condition:	None
Headwall Material:	None
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	16
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	24
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-121-I
Street Name:	SHUTESBURY ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/13/2018
Culvert Condition:	Good
Culvert Diameter:	24
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	22
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	36
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-121-O
Street Name:	SHUTESBURY ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/13/2018
Culvert Condition:	Good
Culvert Diameter:	24
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	22
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	36
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-123-I
Street Name:	VALLEY ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/13/2018
Culvert Condition:	Fair
Culvert Diameter:	36
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	No
Headwall Condition:	None
Headwall Material:	None
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	56
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Dirt/Gravel
Roadway Sags:	No
Depth of Fill	36
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-123-O
Street Name:	VALLEY ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/13/2018
Culvert Condition:	Satisfactory
Culvert Diameter:	36
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	No
Headwall Condition:	None
Headwall Material:	None
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	56
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Dirt/Gravel
Roadway Sags:	No
Depth of Fill	36
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-125-I
Street Name:	BUFFUM ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/12/2018
Culvert Condition:	Good
Culvert Diameter:	0
Culvert Height:	60
Culvert Width:	60
Culvert Shape:	Irregular
Culvert Material:	OTHER
Culvert Bottom Type:	Natural
Culvert Issue:	None
Headwall Present:	No
Headwall Condition:	None
Headwall Material:	None
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	Stone culvert, 60" in upstream side, pipe ends halfway through culvert



Visible Sediment:	No
Screened In:	No
Closest Pole:	5
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	6
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-125-O
Street Name:	BUFFUM ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/12/2018
Culvert Condition:	Good
Culvert Diameter:	0
Culvert Height:	60
Culvert Width:	60
Culvert Shape:	Irregular
Culvert Material:	OTHER
Culvert Bottom Type:	Natural
Culvert Issue:	None
Headwall Present:	No
Headwall Condition:	None
Headwall Material:	None
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	Stone culvert, 60" in upstream side, pipe ends halfway through culvert



Visible Sediment:	No
Screened In:	No
Closest Pole:	5
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	6
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-127-I
Street Name:	VALLEY ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/12/2018
Culvert Condition:	Good
Culvert Diameter:	84
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Good
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	28M
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	6
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-127-O
Street Name:	VALLEY ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/12/2018
Culvert Condition:	Good
Culvert Diameter:	84
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Good
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	28M
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	6
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-128-I
Street Name:	VALLEY ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/12/2018
Culvert Condition:	Good
Culvert Diameter:	36
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Good
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	21
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	36
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-128-O
Street Name:	VALLEY ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/12/2018
Culvert Condition:	Good
Culvert Diameter:	36
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Good
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	Yes
Closest Pole:	21
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	36
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-129-I
Street Name:	VALLEY ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/12/2018
Culvert Condition:	Good
Culvert Diameter:	120
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Natural
Culvert Issue:	None
Headwall Present:	No
Headwall Condition:	None
Headwall Material:	None
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	2 pipes ~120", no access for measurements



Visible Sediment:	No
Screened In:	No
Closest Pole:	6
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	120
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-129-O
Street Name:	VALLEY ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/12/2018
Culvert Condition:	Good
Culvert Diameter:	120
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Natural
Culvert Issue:	None
Headwall Present:	No
Headwall Condition:	None
Headwall Material:	None
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	2 pipes ~120", no access for measurements



Visible Sediment:	No
Screened In:	No
Closest Pole:	6
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	120
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-130-I
Street Name:	HARKNESS ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/13/2018
Culvert Condition:	Satisfactory
Culvert Diameter:	36
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	Yes
Wingwall Material:	Stone
Wingwall Length:	74
Wingwall Condition:	Fair
Scouring:	No
High Water Signs:	No
Inspection Notes:	Nearby bollards w/o rails, poor condition



Visible Sediment:	No
Screened In:	No
Closest Pole:	34
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	24
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-130-O
Street Name:	HARKNESS ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/13/2018
Culvert Condition:	Satisfactory
Culvert Diameter:	36
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	Nearby bollards w/o rails, poor condition



Visible Sediment:	No
Screened In:	No
Closest Pole:	34
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	24
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-131-I
Street Name:	GATES ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/12/2018
Culvert Condition:	Good
Culvert Diameter:	24
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	None
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Dirt/Gravel
Roadway Sags:	No
Depth of Fill	12
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-131-O
Street Name:	GATES ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/12/2018
Culvert Condition:	Fair
Culvert Diameter:	24
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	None
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Dirt/Gravel
Roadway Sags:	No
Depth of Fill	12
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-133-I
Street Name:	AMHERST ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/14/2018
Culvert Condition:	Good
Culvert Diameter:	0
Culvert Height:	120
Culvert Width:	120
Culvert Shape:	Box
Culvert Material:	RCP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	No
Headwall Condition:	None
Headwall Material:	None
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	1 24
Weather Condition:	Cloudy
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	60
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-133-O
Street Name:	AMHERST ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/14/2018
Culvert Condition:	Good
Culvert Diameter:	0
Culvert Height:	120
Culvert Width:	120
Culvert Shape:	Box
Culvert Material:	RCP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	No
Headwall Condition:	None
Headwall Material:	None
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	1 24
Weather Condition:	Cloudy
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	60
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-135-I
Street Name:	COOK ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/12/2018
Culvert Condition:	Good
Culvert Diameter:	0
Culvert Height:	96
Culvert Width:	72
Culvert Shape:	Irregular
Culvert Material:	OTHER
Culvert Bottom Type:	Natural
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Good
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	Stone culvert



Visible Sediment:	No
Screened In:	No
Closest Pole:	None
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Dirt/Gravel
Roadway Sags:	No
Depth of Fill	120
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-135-O
Street Name:	COOK ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/12/2018
Culvert Condition:	Good
Culvert Diameter:	0
Culvert Height:	96
Culvert Width:	72
Culvert Shape:	Irregular
Culvert Material:	OTHER
Culvert Bottom Type:	Natural
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Good
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	Stone culvert



Visible Sediment:	No
Screened In:	No
Closest Pole:	None
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Dirt/Gravel
Roadway Sags:	No
Depth of Fill	120
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-136-I
Street Name:	AMHERST ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/14/2018
Culvert Condition:	Fair
Culvert Diameter:	0
Culvert Height:	60
Culvert Width:	66
Culvert Shape:	Box
Culvert Material:	RCP
Culvert Bottom Type:	Natural
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Concrete
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	Yes
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	104
Weather Condition:	Cloudy
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	60
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-136-O
Street Name:	AMHERST ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/14/2018
Culvert Condition:	Satisfactory
Culvert Diameter:	0
Culvert Height:	60
Culvert Width:	66
Culvert Shape:	Box
Culvert Material:	RCP
Culvert Bottom Type:	Natural
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Good
Headwall Material:	Concrete
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	104
Weather Condition:	Cloudy
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	60
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-137-I
Street Name:	AMHERST ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/14/2018
Culvert Condition:	Poor
Culvert Diameter:	30
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	Pipe bottom rusted out
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Concrete
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	None
Weather Condition:	Cloudy
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	36
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-137-O
Street Name:	AMHERST ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/14/2018
Culvert Condition:	Poor
Culvert Diameter:	30
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	Pipe bottom rusted out
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Concrete
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	1.126
Weather Condition:	Cloudy
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	36
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-138-I
Street Name:	AMHERST ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/14/2018
Culvert Condition:	Poor
Culvert Diameter:	24
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	Pipe bottom starting to rust out
Headwall Present:	Yes
Headwall Condition:	Poor
Headwall Material:	Concrete
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	Yes
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	1 135
Weather Condition:	Cloudy
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	30
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-138-O
Street Name:	AMHERST ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/14/2018
Culvert Condition:	Poor
Culvert Diameter:	24
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	Pipe bottom starting to rust out
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Concrete
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	1 135
Weather Condition:	Cloudy
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	30
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-141-I
Street Name:	KING ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/13/2018
Culvert Condition:	Good
Culvert Diameter:	12
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	2
Weather Condition:	Snow
Stream Condition:	Good
Pavement Condition:	Dirt/Gravel
Roadway Sags:	No
Depth of Fill	24
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-141-O
Street Name:	KING ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/13/2018
Culvert Condition:	Good
Culvert Diameter:	12
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	2
Weather Condition:	Snow
Stream Condition:	Good
Pavement Condition:	Dirt/Gravel
Roadway Sags:	No
Depth of Fill	24
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-152-I
Street Name:	PACKARDVILLE ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/14/2018
Culvert Condition:	Poor
Culvert Diameter:	18
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Natural
Culvert Issue:	Pipe bottom rusted out
Headwall Present:	No
Headwall Condition:	None
Headwall Material:	None
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	73
Weather Condition:	Cloudy
Stream Condition:	Good
Pavement Condition:	Fair
Roadway Sags:	No
Depth of Fill	18
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-152-O
Street Name:	PACKARDVILLE ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/14/2018
Culvert Condition:	Poor
Culvert Diameter:	18
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Natural
Culvert Issue:	Pipe bottom rusted out
Headwall Present:	No
Headwall Condition:	None
Headwall Material:	None
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	73
Weather Condition:	Cloudy
Stream Condition:	Good
Pavement Condition:	Fair
Roadway Sags:	No
Depth of Fill	18
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-153-I
Street Name:	PACKARDVILLE ROAD
Inlet/Outlet	Inlet
Inspection Date:	5/25/2019
Culvert Condition:	Poor
Culvert Diameter:	12
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round-Double
Culvert Material:	CMP
Culvert Bottom Type:	Natural
Culvert Issue:	Rusted pipe
Headwall Present:	No
Headwall Condition:	None
Headwall Material:	None
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	Yes
Inspection Notes:	0



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	72
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Dirt/Gravel
Roadway Sags:	No
Depth of Fill	12
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-153-O
Street Name:	PACKARDVILLE ROAD
Inlet/Outlet	Outlet
Inspection Date:	5/25/2019
Culvert Condition:	Poor
Culvert Diameter:	12
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round-Double
Culvert Material:	CMP
Culvert Bottom Type:	Natural
Culvert Issue:	Rusted pipe
Headwall Present:	No
Headwall Condition:	None
Headwall Material:	None
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	Yes
Inspection Notes:	0



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	72
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Dirt/Gravel
Roadway Sags:	No
Depth of Fill	12
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-163-I
Street Name:	BOYDEN ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/12/2018
Culvert Condition:	Good
Culvert Diameter:	15
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	5
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Dirt/Gravel
Roadway Sags:	No
Depth of Fill	24
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-163-O
Street Name:	BOYDEN ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/12/2018
Culvert Condition:	Very Good
Culvert Diameter:	15
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	5
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Dirt/Gravel
Roadway Sags:	No
Depth of Fill	24
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-168-I
Street Name:	BUFFUM ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/12/2018
Culvert Condition:	Fair
Culvert Diameter:	15
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	Pipe bottom rusted out
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	20
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	24
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-168-O
Street Name:	BUFFUM ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/12/2018
Culvert Condition:	Fair
Culvert Diameter:	15
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	Pipe bottom rusted out
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	20
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	24
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-170-I
Street Name:	OLD PRATTS CORNER ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/12/2018
Culvert Condition:	Fair
Culvert Diameter:	15
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	8
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Dirt/Gravel
Roadway Sags:	No
Depth of Fill	24
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-170-O
Street Name:	OLD PRATTS CORNER ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/12/2018
Culvert Condition:	Good
Culvert Diameter:	15
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	8
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Dirt/Gravel
Roadway Sags:	No
Depth of Fill	24
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-172-I
Street Name:	OLD PRATTS CORNER ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/12/2018
Culvert Condition:	Good
Culvert Diameter:	15
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	HDPE
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	None
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Dirt/Gravel
Roadway Sags:	No
Depth of Fill	30
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-172-O
Street Name:	OLD PRATTS CORNER ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/12/2018
Culvert Condition:	Good
Culvert Diameter:	15
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	HDPE
Culvert Bottom Type:	Engineered
Culvert Issue:	Top of pipe cracked
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	None
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Dirt/Gravel
Roadway Sags:	No
Depth of Fill	30
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-174-I
Street Name:	BUFFUM ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/12/2018
Culvert Condition:	Fair
Culvert Diameter:	30
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	Two 15" pipes



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	17
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	24
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-174-O
Street Name:	BUFFUM ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/12/2018
Culvert Condition:	Poor
Culvert Diameter:	30
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	Pipe bottom rusted
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	Two 15" pipes



Visible Sediment:	No
Screened In:	No
Closest Pole:	17
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	24
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-176-I
Street Name:	BUFFUM ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/12/2018
Culvert Condition:	Poor
Culvert Diameter:	15
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	HDPE
Culvert Bottom Type:	Engineered
Culvert Issue:	Major Blockage
Headwall Present:	No
Headwall Condition:	None
Headwall Material:	None
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	12
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	18
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-176-O
Street Name:	BUFFUM ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/12/2018
Culvert Condition:	Poor
Culvert Diameter:	15
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	HDPE
Culvert Bottom Type:	Engineered
Culvert Issue:	Major Blockage
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	12
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	18
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-178-I
Street Name:	BUFFUM ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/12/2018
Culvert Condition:	Very Good
Culvert Diameter:	15
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	HDPE
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	10
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	18
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-178-O
Street Name:	BUFFUM ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/12/2018
Culvert Condition:	Very Good
Culvert Diameter:	15
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	HDPE
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	10
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	18
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-180-I
Street Name:	BUFFUM ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/12/2018
Culvert Condition:	Good
Culvert Diameter:	24
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	No
Headwall Condition:	None
Headwall Material:	None
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	561
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Fair
Roadway Sags:	No
Depth of Fill	30
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-180-O
Street Name:	BUFFUM ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/12/2018
Culvert Condition:	Good
Culvert Diameter:	24
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	No
Headwall Condition:	None
Headwall Material:	None
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	561
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Fair
Roadway Sags:	No
Depth of Fill	30
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-182-I
Street Name:	BUFFUM ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/12/2018
Culvert Condition:	Good
Culvert Diameter:	21
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	No
Headwall Condition:	None
Headwall Material:	None
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	561
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Fair
Roadway Sags:	No
Depth of Fill	30
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-182-O
Street Name:	BUFFUM ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/12/2018
Culvert Condition:	Good
Culvert Diameter:	21
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	No
Headwall Condition:	None
Headwall Material:	None
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	561
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Fair
Roadway Sags:	No
Depth of Fill	30
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-187-I
Street Name:	GATES ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/12/2018
Culvert Condition:	Good
Culvert Diameter:	24
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	HDPE
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	11
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Dirt/Gravel
Roadway Sags:	No
Depth of Fill	24
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-187-O
Street Name:	GATES ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/12/2018
Culvert Condition:	Good
Culvert Diameter:	24
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	HDPE
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	11
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Dirt/Gravel
Roadway Sags:	No
Depth of Fill	24
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-190-I
Street Name:	VALLEY ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/12/2018
Culvert Condition:	Good
Culvert Diameter:	15
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Poor
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	17
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	30
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-190-O
Street Name:	VALLEY ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/12/2018
Culvert Condition:	Good
Culvert Diameter:	15
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	No
Headwall Condition:	None
Headwall Material:	None
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	17
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	30
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-193-I
Street Name:	SOUTH VALLEY ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/12/2018
Culvert Condition:	Satisfactory
Culvert Diameter:	12
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	Pipe starting to rust
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	23
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Fair
Roadway Sags:	No
Depth of Fill	36
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-193-O
Street Name:	SOUTH VALLEY ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/12/2018
Culvert Condition:	Satisfactory
Culvert Diameter:	12
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	Pipe starting to rust
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	23
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Fair
Roadway Sags:	No
Depth of Fill	48
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-195-I
Street Name:	SOUTH VALLEY ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/12/2018
Culvert Condition:	Serious
Culvert Diameter:	0
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Unknown
Culvert Material:	Unknown
Culvert Bottom Type:	Unknown
Culvert Issue:	Buried at both ends
Headwall Present:	No
Headwall Condition:	None
Headwall Material:	None
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	24
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Fair
Roadway Sags:	No
Depth of Fill	12
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-195-O
Street Name:	SOUTH VALLEY ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/12/2018
Culvert Condition:	Serious
Culvert Diameter:	0
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Unknown
Culvert Material:	Unknown
Culvert Bottom Type:	Unknown
Culvert Issue:	Buried at both ends
Headwall Present:	No
Headwall Condition:	None
Headwall Material:	None
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	24
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Fair
Roadway Sags:	No
Depth of Fill	12
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-197-I
Street Name:	COOK ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/12/2018
Culvert Condition:	Good
Culvert Diameter:	15
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	No
Headwall Condition:	None
Headwall Material:	None
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	81
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Dirt/Gravel
Roadway Sags:	No
Depth of Fill	12
Side Slopes	Flat
Underground Utilities:	No

Outfall ID:	CUL-197-O
Street Name:	COOK ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/12/2018
Culvert Condition:	Good
Culvert Diameter:	15
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	No
Headwall Condition:	None
Headwall Material:	None
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	81
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Dirt/Gravel
Roadway Sags:	No
Depth of Fill	12
Side Slopes	Flat
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-199-I
Street Name:	COOK ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/12/2018
Culvert Condition:	Good
Culvert Diameter:	15
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	No
Headwall Condition:	None
Headwall Material:	None
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	2
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Dirt/Gravel
Roadway Sags:	No
Depth of Fill	12
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-199-O
Street Name:	COOK ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/12/2018
Culvert Condition:	Good
Culvert Diameter:	15
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	No
Headwall Condition:	None
Headwall Material:	None
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	2
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Dirt/Gravel
Roadway Sags:	No
Depth of Fill	12
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-201-I
Street Name:	COOK ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/12/2018
Culvert Condition:	Good
Culvert Diameter:	24
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	3
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Dirt/Gravel
Roadway Sags:	No
Depth of Fill	36
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-201-O
Street Name:	COOK ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/12/2018
Culvert Condition:	Good
Culvert Diameter:	24
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	3
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Dirt/Gravel
Roadway Sags:	No
Depth of Fill	36
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-204-I
Street Name:	VALLEY ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/13/2018
Culvert Condition:	Satisfactory
Culvert Diameter:	36
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	Yes
Wingwall Material:	Stone
Wingwall Length:	48
Wingwall Condition:	Fair
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	33
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Fair
Roadway Sags:	No
Depth of Fill	24
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-204-O
Street Name:	VALLEY ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/13/2018
Culvert Condition:	Satisfactory
Culvert Diameter:	36
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	33
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Fair
Roadway Sags:	No
Depth of Fill	24
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-207-I
Street Name:	VALLEY ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/13/2018
Culvert Condition:	Fair
Culvert Diameter:	12
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	No
Headwall Condition:	None
Headwall Material:	None
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	81
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Dirt/Gravel
Roadway Sags:	No
Depth of Fill	6
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-207-O
Street Name:	VALLEY ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/13/2018
Culvert Condition:	Satisfactory
Culvert Diameter:	12
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	81
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Dirt/Gravel
Roadway Sags:	No
Depth of Fill	6
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-209-I
Street Name:	VALLEY ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/13/2018
Culvert Condition:	Satisfactory
Culvert Diameter:	12
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	No
Headwall Condition:	None
Headwall Material:	None
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	None
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Dirt/Gravel
Roadway Sags:	No
Depth of Fill	6
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-209-O
Street Name:	VALLEY ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/13/2018
Culvert Condition:	Satisfactory
Culvert Diameter:	12
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	No
Headwall Condition:	None
Headwall Material:	None
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	None
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Dirt/Gravel
Roadway Sags:	No
Depth of Fill	6
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-214-I
Street Name:	SHUTESBURY ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/13/2018
Culvert Condition:	Good
Culvert Diameter:	24
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Good
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	None
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	60
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-214-I
Street Name:	SHUTESBURY ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/13/2018
Culvert Condition:	Good
Culvert Diameter:	24
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Good
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	None
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	60
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-216-I
Street Name:	HARKNESS ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/13/2018
Culvert Condition:	Good
Culvert Diameter:	12
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	HDPE
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	No
Headwall Condition:	None
Headwall Material:	None
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	May be private road, no name found



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	None
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Fair
Roadway Sags:	No
Depth of Fill	30
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-216-O
Street Name:	HARKNESS ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/13/2018
Culvert Condition:	Good
Culvert Diameter:	12
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	HDPE
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	No
Headwall Condition:	None
Headwall Material:	None
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	May be private road, no name found



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	None
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Fair
Roadway Sags:	No
Depth of Fill	30
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-219-I
Street Name:	ARNOLD ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/13/2018
Culvert Condition:	Good
Culvert Diameter:	12
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	10T
Weather Condition:	Clear
Stream Condition:	Red algae
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	12
Side Slopes	Flat
Underground Utilities:	No

Outfall ID:	CUL-219-O
Street Name:	ARNOLD ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/13/2018
Culvert Condition:	Good
Culvert Diameter:	12
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	10T
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	12
Side Slopes	Flat
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-221-I
Street Name:	ARNOLD ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/13/2018
Culvert Condition:	Good
Culvert Diameter:	12
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	27
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	12
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-221-O
Street Name:	ARNOLD ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/13/2018
Culvert Condition:	Good
Culvert Diameter:	12
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	27
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	12
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-223-I
Street Name:	ARNOLD ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/13/2018
Culvert Condition:	Good
Culvert Diameter:	18
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	9
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	36
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-223-O
Street Name:	ARNOLD ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/13/2018
Culvert Condition:	Good
Culvert Diameter:	18
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	9
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	36
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-225-I
Street Name:	ARNOLD ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/13/2018
Culvert Condition:	Satisfactory
Culvert Diameter:	12
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	11
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	12
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-225-O
Street Name:	ARNOLD ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/13/2018
Culvert Condition:	Satisfactory
Culvert Diameter:	12
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	11
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	12
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-227-I
Street Name:	ARNOLD ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/13/2018
Culvert Condition:	Good
Culvert Diameter:	12
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	11
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	18
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-227-O
Street Name:	ARNOLD ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/13/2018
Culvert Condition:	Good
Culvert Diameter:	12
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	11
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	18
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-229-I
Street Name:	ARNOLD ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/13/2018
Culvert Condition:	Satisfactory
Culvert Diameter:	12
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	16
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	12
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-229-O
Street Name:	ARNOLD ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/13/2018
Culvert Condition:	Satisfactory
Culvert Diameter:	12
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	16
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	12
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-232-I
Street Name:	BUTTER HILL ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/14/2018
Culvert Condition:	Fair
Culvert Diameter:	15
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	No
Headwall Condition:	None
Headwall Material:	None
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	7
Weather Condition:	Cloudy
Stream Condition:	Good
Pavement Condition:	Fair
Roadway Sags:	No
Depth of Fill	12
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-232-O
Street Name:	BUTTER HILL ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/14/2018
Culvert Condition:	Satisfactory
Culvert Diameter:	15
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	7
Weather Condition:	Cloudy
Stream Condition:	Good
Pavement Condition:	Fair
Roadway Sags:	No
Depth of Fill	12
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-234-I
Street Name:	BUTTER HILL ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/14/2018
Culvert Condition:	Poor
Culvert Diameter:	0
Culvert Height:	12
Culvert Width:	12
Culvert Shape:	Irregular
Culvert Material:	OTHER
Culvert Bottom Type:	Natural
Culvert Issue:	Blockage
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	6 10M
Weather Condition:	Cloudy
Stream Condition:	Good
Pavement Condition:	Poor
Roadway Sags:	No
Depth of Fill	12
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-234-O
Street Name:	BUTTER HILL ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/14/2018
Culvert Condition:	Poor
Culvert Diameter:	0
Culvert Height:	12
Culvert Width:	12
Culvert Shape:	Irregular
Culvert Material:	OTHER
Culvert Bottom Type:	Natural
Culvert Issue:	Blockage
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	6 10M
Weather Condition:	Cloudy
Stream Condition:	Good
Pavement Condition:	Poor
Roadway Sags:	No
Depth of Fill	12
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-236-I
Street Name:	BUTTER HILL ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/14/2018
Culvert Condition:	Fair
Culvert Diameter:	15
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	Pipe bottom starting to rust
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	6 10M
Weather Condition:	Cloudy
Stream Condition:	Good
Pavement Condition:	Poor
Roadway Sags:	No
Depth of Fill	18
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-236-O
Street Name:	BUTTER HILL ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/14/2018
Culvert Condition:	Fair
Culvert Diameter:	15
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	Pipe bottom starting to rust
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	6 10M
Weather Condition:	Cloudy
Stream Condition:	Good
Pavement Condition:	Poor
Roadway Sags:	No
Depth of Fill	18
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-238-I
Street Name:	PACKARDVILLE ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/14/2018
Culvert Condition:	Poor
Culvert Diameter:	18
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	Pipe bottom rusted out
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	10 28S
Weather Condition:	Cloudy
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	24
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-238-O
Street Name:	PACKARDVILLE ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/14/2018
Culvert Condition:	Poor
Culvert Diameter:	18
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	Pipe bottom rusted out
Headwall Present:	Yes
Headwall Condition:	Good
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	10 28S
Weather Condition:	Cloudy
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	24
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-240-I
Street Name:	GULF ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/14/2018
Culvert Condition:	Poor
Culvert Diameter:	12
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	RCP
Culvert Bottom Type:	Engineered
Culvert Issue:	Major blockage
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	12 10
Weather Condition:	Cloudy
Stream Condition:	Good
Pavement Condition:	Fair
Roadway Sags:	No
Depth of Fill	18
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-240-O
Street Name:	GULF ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/14/2018
Culvert Condition:	Poor
Culvert Diameter:	12
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	RCP
Culvert Bottom Type:	Engineered
Culvert Issue:	Major blockage
Headwall Present:	Unknown
Headwall Condition:	Unknown
Headwall Material:	Unknown
Wingwall Present:	Unknown
Wingwall Material:	Unknown
Wingwall Length:	Unknown
Wingwall Condition:	Unknown
Scouring:	No
High Water Signs:	No
Inspection Notes:	Downstream structure buried



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	12 10
Weather Condition:	Cloudy
Stream Condition:	Good
Pavement Condition:	Fair
Roadway Sags:	No
Depth of Fill	18
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-242-I
Street Name:	PACKARDVILLE ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/14/2018
Culvert Condition:	Satisfactory
Culvert Diameter:	18
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	HDPE
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	Yes
Closest Pole:	6M
Weather Condition:	Cloudy
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	24
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-242-O
Street Name:	PACKARDVILLE ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/14/2018
Culvert Condition:	Satisfactory
Culvert Diameter:	18
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	HDPE
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	6M
Weather Condition:	Cloudy
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	24
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-244-I
Street Name:	PACKARDVILLE ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/14/2018
Culvert Condition:	Poor
Culvert Diameter:	15
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	Pipe bottom rusted out
Headwall Present:	No
Headwall Condition:	None
Headwall Material:	None
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	25T
Weather Condition:	Cloudy
Stream Condition:	Good
Pavement Condition:	Fair
Roadway Sags:	No
Depth of Fill	30
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-244-O
Street Name:	PACKARDVILLE ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/14/2018
Culvert Condition:	Poor
Culvert Diameter:	15
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	Engineered
Culvert Issue:	Pipe bottom rusted out
Headwall Present:	No
Headwall Condition:	None
Headwall Material:	None
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	25T
Weather Condition:	Cloudy
Stream Condition:	Good
Pavement Condition:	Fair
Roadway Sags:	No
Depth of Fill	30
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-246-I
Street Name:	PACKARDVILLE ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/14/2018
Culvert Condition:	Unknown
Culvert Diameter:	15
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	HDPE
Culvert Bottom Type:	Engineered
Culvert Issue:	Blockage
Headwall Present:	Unknown
Headwall Condition:	Unknown
Headwall Material:	Unknown
Wingwall Present:	Unknown
Wingwall Material:	Unknown
Wingwall Length:	Unknown
Wingwall Condition:	Unknown
Scouring:	No
High Water Signs:	No
Inspection Notes:	Upstream end buried



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	16
Weather Condition:	Cloudy
Stream Condition:	Blockage
Pavement Condition:	Fair
Roadway Sags:	No
Depth of Fill	12
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-246-O
Street Name:	PACKARDVILLE ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/14/2018
Culvert Condition:	Good
Culvert Diameter:	15
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	HDPE
Culvert Bottom Type:	Engineered
Culvert Issue:	Blockage
Headwall Present:	No
Headwall Condition:	None
Headwall Material:	None
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	16
Weather Condition:	Cloudy
Stream Condition:	Good
Pavement Condition:	Fair
Roadway Sags:	No
Depth of Fill	12
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-248-I
Street Name:	AMHERST ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/14/2018
Culvert Condition:	Good
Culvert Diameter:	24
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	RCP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	No
Headwall Condition:	None
Headwall Material:	None
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	63
Weather Condition:	Cloudy
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	30
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-248-O
Street Name:	AMHERST ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/14/2018
Culvert Condition:	Good
Culvert Diameter:	24
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	RCP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Good
Headwall Material:	Concrete
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	63
Weather Condition:	Cloudy
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	24
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-251-I
Street Name:	AMHERST ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/14/2018
Culvert Condition:	Good
Culvert Diameter:	15
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	RCP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Good
Headwall Material:	Concrete
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	102
Weather Condition:	Cloudy
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	18
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-251-O
Street Name:	AMHERST ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/14/2018
Culvert Condition:	Good
Culvert Diameter:	15
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	RCP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Good
Headwall Material:	Concrete
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	102
Weather Condition:	Cloudy
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	24
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-254-I
Street Name:	AMHERST ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/14/2018
Culvert Condition:	Good
Culvert Diameter:	12
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	RCP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Good
Headwall Material:	Concrete
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	10T
Weather Condition:	Cloudy
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	24
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-254-O
Street Name:	AMHERST ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/14/2018
Culvert Condition:	Good
Culvert Diameter:	12
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	RCP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Good
Headwall Material:	Concrete
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	10T
Weather Condition:	Cloudy
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	24
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-256-I
Street Name:	AMHERST ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/14/2018
Culvert Condition:	Good
Culvert Diameter:	12
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	RCP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Good
Headwall Material:	Concrete
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	1B 122
Weather Condition:	Cloudy
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	18
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-256-O
Street Name:	AMHERST ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/14/2018
Culvert Condition:	Good
Culvert Diameter:	12
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	RCP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Good
Headwall Material:	Concrete
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	1B 122
Weather Condition:	Cloudy
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	18
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-259-I
Street Name:	AMHERST ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/14/2018
Culvert Condition:	Good
Culvert Diameter:	15
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	RCP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Good
Headwall Material:	Concrete
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	129
Weather Condition:	Cloudy
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	18
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-259-O
Street Name:	AMHERST ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/14/2018
Culvert Condition:	Good
Culvert Diameter:	15
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	RCP
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Good
Headwall Material:	Concrete
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	129
Weather Condition:	Cloudy
Stream Condition:	Red algae
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	18
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-261-I
Street Name:	AMHERST ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/14/2018
Culvert Condition:	Fair
Culvert Diameter:	0
Culvert Height:	24
Culvert Width:	24
Culvert Shape:	Box
Culvert Material:	RCP
Culvert Bottom Type:	Natural
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Unknown
Headwall Material:	Concrete
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	Upstream structure under ice sheet



Visible Sediment:	No
Screened In:	No
Closest Pole:	132
Weather Condition:	Cloudy
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	24
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-261-O
Street Name:	AMHERST ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/14/2018
Culvert Condition:	Satisfactory
Culvert Diameter:	0
Culvert Height:	24
Culvert Width:	24
Culvert Shape:	Box
Culvert Material:	RCP
Culvert Bottom Type:	Natural
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Concrete
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	132
Weather Condition:	Cloudy
Stream Condition:	Good
Pavement Condition:	Good
Roadway Sags:	No
Depth of Fill	36
Side Slopes	Sloped
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-265-I
Street Name:	PACKARDVILLE ROAD
Inlet/Outlet	Inlet
Inspection Date:	12/14/2018
Culvert Condition:	Satisfactory
Culvert Diameter:	15
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	HDPE
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	No
Headwall Condition:	None
Headwall Material:	None
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	19 77
Weather Condition:	Cloudy
Stream Condition:	Good
Pavement Condition:	Poor
Roadway Sags:	No
Depth of Fill	24
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-265-O
Street Name:	PACKARDVILLE ROAD
Inlet/Outlet	Outlet
Inspection Date:	12/14/2018
Culvert Condition:	Satisfactory
Culvert Diameter:	15
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	HDPE
Culvert Bottom Type:	Engineered
Culvert Issue:	None
Headwall Present:	No
Headwall Condition:	None
Headwall Material:	None
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	No
Screened In:	No
Closest Pole:	19 77
Weather Condition:	Cloudy
Stream Condition:	Good
Pavement Condition:	Poor
Roadway Sags:	No
Depth of Fill	24
Side Slopes	Flat
Underground Utilities:	No

Town of Pelham, Massachusetts

Stormwater Mapping - Culvert Inspections

Outfall ID:	CUL-266-I
Street Name:	QUARRY ROAD
Inlet/Outlet	Inlet
Inspection Date:	5/24/2019
Culvert Condition:	Fair
Culvert Diameter:	24
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	N/A
Culvert Issue:	iment buildup, headwall deteriorat
Headwall Present:	Yes
Headwall Condition:	Poor
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	42
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Dirt/Gravel
Roadway Sags:	No
Depth of Fill	60
Side Slopes	Sloped
Underground Utilities:	No

Outfall ID:	CUL-266-O
Street Name:	QUARRY ROAD
Inlet/Outlet	Outlet
Inspection Date:	5/24/2019
Culvert Condition:	Fair
Culvert Diameter:	24
Culvert Height:	0
Culvert Width:	0
Culvert Shape:	Round
Culvert Material:	CMP
Culvert Bottom Type:	N/A
Culvert Issue:	None
Headwall Present:	Yes
Headwall Condition:	Fair
Headwall Material:	Stone
Wingwall Present:	No
Wingwall Material:	None
Wingwall Length:	0
Wingwall Condition:	None
Scouring:	No
High Water Signs:	No
Inspection Notes:	0



Visible Sediment:	Yes
Screened In:	No
Closest Pole:	42
Weather Condition:	Clear
Stream Condition:	Good
Pavement Condition:	Dirt/Gravel
Roadway Sags:	No
Depth of Fill	60
Side Slopes	Sloped
Underground Utilities:	No